

MANUAL SET-UP AND INSTALLATION INSTRUCTIONS

- 1.0 PETKIT P2 Activity Tracker User Guide
 - 1.1 Components
- 2.0 Device Setup and Getting Started
 - 2.1 Application Installation
 - 2.2 Create a profile
 - 2.3 Pairing and Connecting your device
- 3.0 Warranty

1.0 PETKIT P2 Activity Tracker User Guide:

The below user guide will walk you through proper setup and installation instructions.

1.1 Components:

1 (Piece) PETKIT P2 Activity Tracker. 2 (Pieces) sized rubberized collar attachment connectors. 1 (Piece) CR2 included battery. 1 (Piece) Protective shell P2 casing. 1 (Piece) included screwdriver.

2.0 Device Setup and Getting Started

Using the included screwdriver, open and insert the included battery inside the P2 Tracker Device.

2.1 Application Installation

If you're using an Apple IOS device visit the 'App Store', and if you're using an Android device visit the 'Google Play' store. In the search field type "Petkit". Once you've located the application, proceed to download the App.

2.2 Create a profile

Prior to pairing your device you'll be prompted to create a profile or multiple profiles for your pet/s, such as nickname/s, breed, birthday, weight, profile photo, and active levels.

2.3 Pairing and Connecting your device

First, please make sure your Bluetooth is enabled, then visit the home screen of the PETKIT application and tap on '+ Add PETKIT device' then select 'FIT'. Your smart device will begin searching for nearby P2 FIT devices, once your FIT is located an LED light will begin blinking and you'll be prompted to pair. You're all set!

3.0 Warranty

If product is proven damaged, defective or broken, manufacturer will provide a 1 Year Warranty from date of purchase with proof of purchase. Please reach out to us via email at info@petkit.us. Include place of purchase, order number, date of purchase and reason for the return. A member of our troubleshooting team will try to resolve any malfunctions. Once we process the return, we'll issue a return label and adjust payment as needed.